

## BS6696T | TAPED HI VIS COOL LIGHTWEIGHT SHIRT



Yellow/Pink  
(TT33)



Orange/Pink  
(TT34)



Yellow/Navy  
(TT01)



Orange/Navy  
(TT02)



Yellow/Khaki  
(TT16)



Yellow/Charcoal  
(TT23)



Lime/Charcoal  
(TT36)



Yellow/Royal  
(TT43)

Vertical cotton mesh  
back ventilation

Underarm cotton  
mesh ventilation

Two piece contrast coloured  
structured collar

Pen division on left  
chest pocket

Two chest pockets with  
button down flaps

Reflective taped hoop  
pattern

Single turned centre  
front opening

Two button adjustable  
sleeve cuff

Shaped curved hem



### FEATURES

- / Reflective taped hoop pattern
- / Two chest pockets with button down flaps and pen division
- / Two piece contrast coloured structured collar
- / Vertical cotton mesh back ventilation
- / Underarm cotton mesh ventilation
- / Left pocket with pen division
- / Two button adjustable sleeve cuff
- / Platinum Partner of NBCF embroidery (TT33 & TT34 colourways only)
- / Bisley exclusive Fresche® antimicrobial treatment to prevent against bacteria, mould and viruses

### COLOURS

Yellow/Navy (TT01)  
Orange/Navy (TT02)  
Yellow/Khaki (TT16)  
Yellow/Charcoal (TT23)  
Lime/Charcoal (TT36)  
Yellow/Royal (TT43)  
Yellow/Pink (TT33)  
Orange/Pink (TT34)

### SIZES

S - 6XL  
XS - 6XL (TT01 and TT02 only)  
Traditional Fit

### FABRIC

100% Cotton Preshrunk Drill  
155gsm

100% Cotton Open Mesh

### AUSTRALIAN AND INTERNATIONAL STANDARDS

- / **AS/NZS 2621:1998** Textiles - Guide to the Selection of Correct Care Labelling Instructions from AS/NZS 1957
- / **AS/NZS 2392:1999** Textiles - Labelling of Clothing, Household Textiles & Furnishing
- / **AS/NZS 1957:1998** Textiles - Care Labelling
- / **AS/NZS 2622:1996** Textiles Products - Fibre Content Labelling
- / **AS/NZS 4399:2017** Sun Protection Clothing - Evaluation and Classification
- / **AS/NZS 1906.4:2010** Hi Visibility Materials For Safety Garments
- / **AS/NZS 4602.1:2011** Hi Visibility Safety Garments. Garments for High Risk Application
- / **AS/NZS 1020:1995** The Control of Undesirable Static Electricity
- / **ASTM D5489-07** Standard Guide for Care Labelling Code Using Symbols for Care Instructions on Textile Products
- / **ISO 14184-1** Textiles - Determination of Formaldehyde - Part 1: Free and Hydrolized Formaldehyde (Water Extraction Method)

